

16 June 2022

Supply disruption – BD Ultra Touch wingset

BD life sciences have reported significant supply and logistical disruptions that are impacting their ability to provide timely delivery of the Push Button Blood Collection sets and Ultra Touch Push Button sets into Australia.

The following SA Health Catalogue item has been adversely impacted:

- 367364 (23G Ultra Touch wingset)

In the interim, it is recommended that the following substitute product be used:

- BD Vacutainer™ Safety-Lok™ Blood Collection Set 23G x.75, 12" tubing with luer (**BD material number 367288**). Note – steps are currently being taken to add this product to the ORACLE catalogue.

Additionally, it is recommended that end users monitor stock levels of Push Button and Ultra Touch collection sets to limit their use where possible.

Regards,

Dr Sophia Otto

Clinical Service Director

SA Pathology

www.sapathology.sa.gov.au



Government of South Australia

SA Health